







OWNER:  شرکت سست موبلی آوند ایرانیان (سهامی خاص)	BUSHEHR PETROCHEMICAL COMPANY MEG PLANT						EPC CONTRACTOR:  Chagalesh-Enerchimi-Steam Joint Venture BUPC-MEG PLANT PROJECT		
	MC :  شرکت سست موبلی آوند ایرانیان (سهامی خاص)	TWO YEARS SPARE PARTS LIST							
Owner Document Number: 17811-42	Project	Area	Phase	Unit	Dis.	Doc.	Seq.	Contract No : 52-98/445	
	BU	20	VD	303	ME	LST	0054	Rev.: 02	Page 1 of 5

TWO YEARS SPARE PARTS LIST

 شرکت سست موبلی آوند ایرانیان (سهامی خاص)	 Chagalesh-Enerchimi-Steam Joint Venture BUPC-MEG PLANT PROJECT	BUSHEHR PETROCHEMICAL COMPANY MEG PLANT
Document Review		
Issue Purpose:		IFA
Result Code: AP,AN,CM,RE,NC		CM
Next Status : IFC,IFA,IFI,AFC,AB		IFA
Responsible Department		MECHANICAL
Commented Date		Jul.29,2023
Approval or review hereunder shall not be construed to relieve Vendor / Subcontractor of his responsibilities and liability under the contract.		

Rev.	Date	Purpose of Issue	Prepared	Checked	Approved	AC Code
02	14/07/2023	Issue For Approve	MC	KP	JR	
01	07/11/2022	Issue For Approve	MC	KP	JR	
00	10/06/2022	Issue For Approve	KP	CL	JR	
					Class: 1	Phase: P



BUSHEHR PETROCHEMICAL COMPANY MEG PLANT

فهرست قطعات یدکی و اقلام مشابه

SPARE PARTS LIST AND INTERCHANGEABILITY RECORD FOR

Table with columns: EQUIPMENT CLASS, EQUIPMENT REO, MANUFACTURERS MODEL, MANUFACTURERS SERIAL NO., NO OF UNIT, UNIT, DESCRIPTION OF PARTS, DRAWING/ REF.NO., Manufacturers Real part No., Material, Recommended by manufacturer, Recommended by contractor, 2-Year spares, Quantity to be supplied, MESC NO., Classification of parts, Unit Price in USD, Total Price in USD, Remarks, Item No.

Other main equipment of compressor 1002 shall be written here in individual column(Electrical motor, pulsation dampener, heat exchanger, instrumentation)

Description is hide.

Two component for one compressor 2x1=2 Above criteria shall be used for all cells.

- Radial oil seal gaskets (893, 840) for compressor 1002 are missing. - Liner of both stages are missing. - Oil gland seal / wiper is missing. - Gland gas (1027) is missing. - Tube, bolts and gaskets for heat exchanger of C-10002 is missing. Interstage and after cooler shall be written separately.

Two, as per compressor data sheet.

Stage one or two shall be specified. Please use following description since spring is needed: - Suction valve (complete set) - Discharge valve (complete set)

6 as per contract (material requisition)

